

1A: East Facet



1B: Northeast Facet



1C: North Facet



1D: Northwest Facet



1E: West Facet



1F: Southwest Facet



1G: South Facet



1H: Southeast Facet

Key to Survey Codes

Condition	Symbol	Fault Type		Severity	Amount
Corroded		Srf	Surface	Not applicable	Area in sq. ft.
		Pit	Pitted		Area in sq. ft.
		Prf	Perforated		Area in sq. ft.
		Dnt	Dented		
Damaged		Pnc	Punctured	Not applicable	Area in sq. ft.
		Trn	Torn		
Paint Failed		PF	Paint Failed	Not applicable	Length in lin. ft.
Seams Failed		FstF	Fastener Failed	Not applicable	Count
		SldF	Solder Failed		Length in lin. ft.
Soiled/Stained		Pnt	Paint	Not applicable	Area in sq. ft.
		Rst	Rust		
Unsecured		L	Loose	Not applicable	Area in sq. ft.
		M	Missing		
		R	Removed		

Key to Symbols

Most annotations are comprised of box symbols and text labels. Typical or widespread conditions may not include box symbols.

Each text label includes a fault code describing the type of conditon, and if applicable, a severity code and Picture Link.

This box symbol indicates an area of surface corrosion, which was photographed

Text label: Srf

Picture Link:

Key Plan



VERTICAL ACCESS

SURVEYED USING tpas
MAY 2007 BY: EK, KS, MG

PO Box 4135 Ithaca, NY 14850
607.257.4049 www.verticalaccess.com

ISSUE DATE: MAY 2007

ELEVATIONS
FACADE SURVEY

BACKGROUND DRAWING: CLIENT PROVIDED, AUTOCAD VECTOR SCALE: REDUCED PLOT, NOT TO SCALE

Building Use: Religious
Architectural Style: Gothic Fleche
Materials: Sheet Metal, Bronze

VA PROJECT NUMBER:

1